

Lead in School Drinking Water Report

Shuksan Middle School

Date(s) collected: 2023-10-13, 2023-11-07

Date(s) analyzed: 2023-11-01, 2023-12-14

Sample ID	Building Name	Fixture Type	Housing Location	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
	Main Building	Pot Filler		Kitchen	Right of burners	Tap	13
				Kitchen	Dishwashing sink right 2 of 2	Tap	6
374334	Main Building	Fountain/Tap Combo		Rm107	Only sink		
	Main Building	Fountain/Tap Combo		Rm211	Only sink	Water Fountain	5
374309	Main Building	Sink -					

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
	Building	Combo		windows 1 of 2	Fountain	
374306	Main Building	Sink - Multi-Compartment	Kitchen	Dishwashing sink left 1 of 2	Tap	3
374322	Main Building	Sink	Art Room	Closest to front door left 1 of 2	Tap	3
374402	Main Building	Fountain/Tap Combo	Rm217	Only sink	Water Fountain	3
374311	Main Building	Sink	Cafeteria	Sink in closet next to microwave	Tap	2
374332	Main Building	Fountain/Tap Combo	Sixth Grade Common Area	Only sink	Water Fountain	2
374336	Main Building	Fountain/Tap Combo	Rm108	Only sink	Water Fountain	2
374338	Main Building	Fountain/Tap Combo	Rm219	Only sink	Tap	2
374390	Main Building	Fountain/Tap Combo	Rm210	Only sink	Water Fountain	2
374400	Main Building	Fountain/Tap Combo	Rm216	Only sink	Water Fountain	2
374406	Main Building	Fountain/Tap Combo	Rm201	Only sink	Water Fountain	2
374408	Main Building	Fountain/Tap Combo	Rm202	Only sink	Water Fountain	2
374330	Main Building	Sink	Rm 112 Science	Next to teachers desk	Tap	1
374333	Main Building	Fountain/Tap Combo	Rm107	Only sink	Tap	1
374384	Main Building	Fountain/Tap Combo	Rm207	Only sink	Water Fountain	1
374388	Main Building	Fountain/Tap Combo	Rm208	Right facing windows 2 of 2	Water Fountain	1
374396	Main	Sink	Rm214	Next to	Tap	1

