

# Lead in School Drinking Water Report

## Kulshan Middle School

Date(s) collected: 202311-21

Date(s) analyzed: 202312-28, 2023-12-29

Sample ID	Building Name	Fixture Type	Housing	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
386347	Main Building	Sink - Multi - Compartment		Rm301	4th right of fridge 4of7	Tap	12
386195	Main Building	Sink		Kitchen	Near serving line	Tap	10
386193	Main Building	Sink		Kitchen	Right of large stand mixer	Tap	8
386355	Main Building	Sink		Library	Puzzle office	Tap	7
386199	Main Building	Sink		Wood Shop	Right 2 of 2	Tap	5
386204	Main Building	Sink		Rm111	Only sink	Tap	4

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
	Building	Combo			Fountain	
386210	Main Building	Fountain/Tap Combo	Rm208	Only sink	Tap	3
386344	Main Building	Sink - Multi-Compartment	Rm301	Right of		



Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
		Filler		303&308	Filler	
386354	Main Building	Fountain - Multi - Level with Bottle Filler	Hallway	Left of classrooms 303&308	Water Fountain	<1
386356	Gym Building	Fountain - Multi - Level with Bottle Filler	Hallway	Right of girls locker room	Water Bottle Filler	<1
386357	Gym Building	Fountain - Multi - Level with Bottle Filler	Hallway	Right of girls locker room (left broken)	Water Fountain	<1

#### EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: